

90

.




FIGURE 2

in-line front-of-line portion 300A

V/C 302 V/C 302

D/A	cure	plasma	W/B	plasma
304	306	308	310	312

in-line end-of-line portion 300B


V/C	V/C	V/C
302	302	302

mold	PMC	SBA	saw	sort
314	316	318	320	322

in-line finish portion 300C

V/C	V/C	V/C
302	302	302

mark	FVI	T/R
324	326	328



7 Figure




Figure 5






FIGURE 6





1:

FIGURE 8




FIGURE 9




FIGURE 10




FIGURE 11




FIGURE 12

